

STATE OF OREGON
MONITORING WELL REPORT
(as required by ORS 537.765 & OAR 690-240-095)

MULT
3806

Start Card #

58374

(1) OWNER/PROJECT:

WELL NO.

MW#2

Name

Address

City

State

Zip

(2) TYPE OF WORK:

- ☒ New construction ☐ Repair ☐ Recondition
☐ Conversion ☐ Deepening ☐ Abandonment

(3) DRILLING METHOD

- ☐ Rotary Air ☐ Rotary Mud ☐ Cable
☒ Hollow Stem Auger ☐ Other


(4) BORE HOLE CONSTRUCTION

Yes No

Special Standards

Depth of completed well

20'



(6) LOCATION OF WELL By legal description

Well Location: County

Township

Range

Section

1. NE 1/4 of SE 1/4 of above section.

2. Street address of well location

3. Tax lot number of well location

(7) STATIC WATER LEVEL:

7 Ft. below land surface.

Artesian Pressure lb/sq. in.

Date

Date

(8) WATER BEARING ZONES:

Depth at which water was first found

7'

From	To	Est. Flow Rate	SWL
7'	20'	7	7'

(9) WELL LOG:

Ground elevation

Material	From	To	SWL
Sand, light brown, loose, dry, medium grained	0'	2.5'	
Sandy Silty Gravel, brown, dense, damp, fine to coarse rounded gravel, medium grained sand, nodular	2.5'	7.5'	7'
Gravel, Gray, very dense, saturated, fine to medium sized, rounded	7.5'	12.5'	
Sand, Gray, loose, saturated, medium grained	12.5'	17.5'	
Black, nodular	17.5'	20'	
Heaving Sand			

Date started 10/20/93

Completed

10/20/93

(5) WELL TEST:

- ☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

Permeability Yield GPM

Conductivity PH

Temperature of water 14°C °F/C Depth artesian flow found ft.

Was water analysis done? ☒ Yes ☐ No

By whom? Century West

Depth of strata to be analyzed. From 7' ft. to 20' ft.

Remarks:

(unbonded) Monitor Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to the best knowledge and belief.

MWC Number
Signed Date

(bonded) Monitor Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

MWC Number 10013
Signed Randy L. Crisman Date 11/20/93

USEPA SF

ing Geologist/Engineer

Ingram Paul

FIRST COPY-WATER RESOURCES DEPARTMENT

SECOND COPY-CONSTRUCTOR

THIRD COPY-CUSTOMER




1286492

Port of Portland
Terminal 5
Blue Lagoon

MULT 3806

10/19/93



MW #1 / 58373
MW #2 / 58374
MW #3 / 60130
MW #4 / 60131

Post-Net brand fax transmittal memo 7671		# of pages > 1
To	Randy [unclear]	
From	Eric Collins	
Co.	CRISMAN	
Co.	CNE	
Dept.	Phone 236-6078	
Fax 620-1248	Fax 2	